

Advanced Turbine Support

MS7001FA Lift Oil Line Failure

PURPOSE

To inform users of potential lift oil line failures.

UNIT TYPE


This newsletter addresses the MS7001FA.

HISTORY

There have been numerous lift oil line failures throughout the fleet.

RECOMMENDATION

Users should have ATS perform a borescope inspection of the lift oil lines at the earliest opportunity.



This photograph shows where the stainless braid has failed on one of the lift oil lines.



This photograph shows a budge in one of the lift oil lines.